

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

19th September, 1966.

C.
DD/JW

Dear Sirs,

M.S. "PATELLA"

This ship was surveyed by the Society's Curacao Surveyor between 3rd and 4th August, at which time the main engine No.2. starboard tie bolt was found to be broken. Temporary repairs were carried out, but it was recommended that this tie bolt be renewed by the end of May, 1967.

The Committee have, therefore, continued the ships class subject, inter alia, to this matter receiving attention by that time.

Yours faithfully,

pro Classification Manager

Messrs. Shell Tankers (U.K.) Ltd.,
Shell Centre,
LONDON, S.E.1.



© 2020

Lloyd's Register
Foundation

004630-004634-0285