

PT

PT

27 JAN 1965

Ship's name "PATELLA"

Port SLD

No A509

Last survey date 1.12.64

Class is subject to

NONE

S.R.L. Appendix (as before ~~CXXXXXX~~)

Nature of present survey (afloat and in drydock)

~~XXXXXXXXXXXXX~~
Docking. Damage (cause not stated) involving side shell plating etc, (p & s). Wear and tear repairs. Removal of Cathodic anodes from all cargo tanks.

Recommendation SUBMITTED record of DS 12.64 be assigned, subject to set in shell plates G.11, H.11 & 12 (p.s. from aft) being specially examined and dealt with as necessary next drydocking.

DS 12.64 Subject.

S.R.L. APPENDIX (AMENDED)

H.10 & 13, J.15 (s.s. fwd) H.7 & 8, J.10. (p.s. amids) slightly indented.

© 2020 Lloyd's Register Foundation

Development Sect
1/2/65

30/12/64

TO NOTE

004630-004634-0311