

The Classis Subject to the console supporting main engine attached
pump covers being examined before the end of 3/57 also take
LP cylinder cover being further examined before the end 2 E
of 8/57

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

29 JAN 1957

IP'S NAME

HEINDAL

REPORT

No.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

of Survey COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS

This Survey ^{BS.} due 9.56 ~~now~~ partly held 9/56

now

completed, and the following repairs carried out (due to

): -

It is submitted the vessel is eligible to remain as classed, with
notation of BS. 9.56 as recommended ^{Subject} ~~as above.~~



© 2020

Lloyd's Register
Foundation

004635-004644-0235