

On date of rigging examination
the decision to put in new
Topmasts was already made.
Also to supply PT & STD
SAMSON POSTS with new
stays on account of
lengthening the derrick attached
to same. On both masts
Shrouds are in rusty
condition but serviceable.
MAIN STAY is not of fixed

Corrected © 2020

g. Lindores

Lloyd's Register
Foundation

004635-004641-0248