

1

Received from Chief Surveyors _____

Sent to Chief Surveyors _____

VESSEL'S NAME Stl & "KERMA"

Report

SlNo. 48411**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

1st Entry

When due

Revised Rule

✠ 100 A. I. (Steel).

1 D^c (Stl).

Cell D.B. 324' 1058t, F.P.T. 140t, A.P.T. 115t

F.K, 6 B.H, pt-cen, Lloyd A & CP

P 28', B 105', F 36'.

It is enclosed the semi-hot beam has been fitted to the appropriate mchhead and that the height of the outside tank brackets is as approved but the surveyor should be requested to state if this is so.

See letter
Lloyd's 4/10/28
MS.
1/10/28.
© 2020
Lloyd's Register
Foundation
004635-004641-0267