

s/s "HILARY"

Liv. 149787 & 8

An additional cargo chamber installed in accordance with approved plans, etc.

It is submitted that a certificate be prepared as requested with the Record.

+ LLOYD'S R.M.C.

RS 6/58

≠

↖
& 5 lower deck relation.

with amended temp. notation as per endorsement of 11/8/58

The Surveyors should be informed that, according to our records, the starboard gas compressor has not been examined since the plant was installed and they should be asked to deal with this matter as soon as possible.

our records are as follows:- P.Aft 5/57

F.Outer and A.Outer (presumed same as P. Aft.) 6/68.

CERTIFICATE WRITTEN. 2/8/58

20.8.58

Lloyd's Register Foundation

004642-004645-0169