

SHIP'S NAME

PORT WYNDHAMPORT LIV.No. 169111.app. --- (M)1st
24. 8. 66 LAST SURVEY DATE 25. 8. 66.

CLASS IS SUBJECT TO

- + 1 P.A. aux engine NO3 cyl jacket (M/L 8.64) being examined before the end of 11.66.
- + 2 Outlet air compressor C.I. combined L.P./M.P. Piston being specially examined & dealt with as necessary by end of 11.66.
- + 3 Repaired oil seal casting of the aft O.F. Transfer Pump being re-examined by 6.67 (12 mos limit).
- + A Inlet crosshead guide (M/L 1.66) and entallature (fractured at bottom landing of inlet crankcase door) of the outlet manoeuvring air compressor being re-examined and dealt with as considered necessary by 9.66 (6 mos limit).
- + 5 Temporary electric power & lighting leads in E.R. being specially examined & dealt with as necessary upon ship's return to U.K.
- + 6 Condenser S.W. cooling overboard discharge valve chest being renewed at next dry-docking.

C S(M) advanced.

It is submitted that this vessel is eligible to remain as **CLASSED**.

Subject as above.



© 2020
Lloyd's Register
Foundation