

XXXXXXXXXX

LONDON OUTDOOR.

8th November, 1965.

PORT WYNDHAM

8702

Subject to set up and indented keel plates Nos. 8 & 9 from aft being speceally examined and dealt with as necessary next drydocking and to no.4 hold insulated tank top at the fore end between frame 71, (p & s) and bulkhead 74 being specially examined for oil leakage and dealt with as necessary on ship return to the U.K. from present voyage by 11.65. No.4 O.F. D.B. tanks in way not to be pressed up mean time.

See No. 243 Subject to, that the repaired oil end casting of aft OF transfer pump be re-examined and dealt with as necessary on vessels return to U.K.

See No. 16

Nil

5 but A.B.S. 5.65

Nil



© 2020

Lloyd's Register
Foundation

004642-004645-0272