

18 OCT 1965

MEL	22880
ADL	7927
WLN	10864
AUK	12335

SHIP'S NAME "PORT WYNDHAM"

PORT

No.

LAST SURVEY DATE 11.9.65.

CLASS IS SUBJECT TO :-

1. Port aft auxiliary engine No. 3 cylinder jacket (M.L. 8.64) being examined before the end of 11.65.
2. Port forward auxiliary engine No. 4 entablature (M.L. 10.64) being examined by end of 5.66.
3. Outboard air compressor cast iron combined LP/MP piston be specially examined and dealt with as necessary before the end of 11.65.
4. Starboard main engine No. 1 forward side crosshead pin be specially examined and dealt with as necessary before the end of 11.65.

ABS' due 3.65 now ~~total~~ completed (commenced 5.65)  
CSM advanced

Surveyor reports aft oil fuel transfer pump oil end casting fractured in way of previous repair. Casting removed to workshops, defective welding cut out & casting re-welded. Hydraulically tested on completion & considered satisfactory meantime & Surveyor recommends that the repaired oil end

SHIP'S NAME

PORT

No.

178 OCT 1965

LAST SURVEY DATE

CLASS IS SUBJECT TO

Casting of aft OF transfer pump be re-examined  
& dealt with as necessary on vessels return  
to U.K.

It is submitted that this  
vessel is eligible for THE  
RECORD. ABS 5-65 now

15  
10  
65.

subject as above & as now recommended.



© 2020

Lloyd's Register  
Foundation

No declaration received