


COPY

## LLOYD'S REGISTER OF SHIPPING

Port Adelaide, Sth. Aust.Date 5th August, 1965.

This is to Certify that I have

surveyed the T.S.M.V. "PORT WYNDDHAM", 8702 Gross tons of London on the 3rd August, 1965 and subsequently, whilst lying afloat at this port, for oil fuel leakage in way of the No.4 Insulated Hold bilges, port and starboard, and for pressure testing of No.1 double-bottom tank, No.1 Insulated Hold.

and that I am transmitting to the Committee of Lloyd's Register of Shipping,

London, a report, stating that all repairs recommended by me have been completed

to my satisfaction, also that I am recommending that she be continued as classed without fresh record of survey subject to the No.4 Hold insulated tanktop at the fore-end between bulkhead No.74 and frame No. 71 (measured from aft), port & starboard, being specially examined for oil fuel leakage and dealt with as necessary on the vessel's return to the U.K. this voyage or by 11/65 (3 months limit), the No.4 oil fuel double-bottom tanks in way not being pressed up meanwhile and to the other conditions at present attached to the vessel's class being dealt with as previously recommended but without the condition of class relating to no cargo being carried in No.1 Hold until No.1 double-bottom tank has been dealt with as necessary.

*S.R. Thomas*  
(Sgd.) S.R. Thomas.

Surveyor to Lloyd's Register of Shipping

## KEY TO ABBREVIATIONS

AS Annual Survey  
BiS Biennial Survey  
DS Docking Survey  
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey  
SS(Dr) Hull Special Survey (Drilling)  
SS(M) Hull Special Survey (Modified)  
CSH Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

CERT. 3-4M 3/54-1 R.O'S.

004642-004645-0285

© 2020  
Lloyd's Register  
Foundation