

~~XXXXXX~~

24 JUN 1965

Ship's name "PORT WYNDHAM"

Port

Lon.

No. 154141

Last survey date 15.5.65.

Class is subject to

set up and indented keel plates  
Nos.8 & 9 from aft being specially examined and dealt with  
as necessary next drydocking.

*+ ABS 565 on completion*

S.R.L. Appendix (~~xxxxxxxxxxxx~~ none)

Nature of present survey (afloat and in drydock)

Docking: Deferred repairs due to suspected fracture in  
air pipe to No.1 D.B.tank.

Recommendation

SUBMITTED record of 'DS 5,65' be assigned  
subject as above, and to cargo not being  
carried in No.1 hold until leakage from  
No.1 D.B.tank has been dealt with as  
necessary on arrival at Cornerbrook, Nfl.

DS 5,65 Subject



© 2020

Lloyd's Register  
Foundation

*fy*  
*8/6/65*