



LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

55, Fawcett Street, Sunderland

9th May, 1950.

Telephone: Sunderland 4093 (2 Lines)

RECEIVED

10 MAY 1950

AND.....

Communications to be addressed to
THE SURVEYORS

Reference

S

Dear Sir,


With reference to your classing letter of 5th instant regarding Sunderland Report 35331 "SOYA CHRISTINA", we have to confirm that the diameter of the L.P. cylinder is 73" as stated on the report and the propeller diameter is 17'7 $\frac{1}{4}$ ". The figure 14'7 $\frac{1}{4}$ " given on the report is a clerical error, which it is regretted was not observed when the report was checked.

The crankshaft is identical with that approved for Messrs G.Clark's Contract 1448 (Short Bros.Yard No. 498) on 8th March 1948.

Yours faithfully,
THE SURVEYORS,

PER:

The Secretary,
LONDON.



Lloyd's Register
Foundation

004653004661-0114

led(FE) 17/4.

Referred to Mr. Perris

For Engineer Surveyors (F.E. Rpts.) to note

Noted Self 11/5/50



© 2020

Lloyd's Register
Foundation