

Gloucester

Gls 64110 Alce

It is concluded that the Surveyors  
checked the spare gear on board & that bronze sealed  
hubs are fitted to the couplers as required  
but this requires confirmation

*[Signature]*

Lloyd's Register  
Foundation

7/8/41

004653 - 004661 - 0247  
Yours faithfully,