

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex  
Address { Overseas: Committee, London, E.C.3

Telephone: 01-709 9166  
Telex No.: 24305

C  
AP/PB

8th January 1968.

Dear Sirs,

## CLASSING LETTER

10848 "TOMAR" As recommended, except that a notation of CSM 9.67 has previously been assigned.

According to the records in this Office the following machinery items have not been surveyed for more than five years:-

Boiler oil service pumps and heaters.  
Main engine H.V.F. heaters (if fitted).

In the circumstances I shall be glad if you will ascertain for the information of the Committee and let me know, by what definite date the Owners propose to have the above outstanding items dealt with.

The following machinery items become due for examination by the times stated:-

Main engine no. 3 cylinder, cover, piston and rod, valves and gears 2.68.  
Main engine no. 9 connecting rod, top end and guide 6.68.  
Main engine no. 1 crankpins and bearing 10.68.  
Main engine no. 2 main bearing and journal 6.68.  
Main engine no. 4 main bearing and journal 9.68.  
Separate oil fuel tanks 5.68.



© 2020

contd ...../

Lloyd's Register  
Foundation

004684.004692-0088 1/2



Please asvise the Owners accordingly and inform them that it is a requirement of the Society's Rules that the interval between examinations of all machinery items must not exceed five years.

I acknowledge receipt of your letter dated the 20th December 1967 the contents of which have been noted.

A classification Certificate in respect of the hull will be forwarded in due course for onward transmission to the Owners.

Yours faithfully,

Pro Classification Manager

The Surveyors  
OSLO



© 2020

Lloyd's Register  
Foundation

00882/2