



© 2020

Lloyd's Register
Foundation



WILTON-FIJENNOORD

SCHIEDAM - HOLLAND

COPYRIGHT WF NADRUK VERBODEN

Tomas

Crack after veeding out stb. side.
coupling flange of stern frame.

Bij nabestelling opgeven Neg. Nr. N246 / 4

Datum Order Nr. 5131

2/MS

Tomas

TO ACCOMPANY

Rob.

Dated

9/63

SUBJECT:-

© 2020

Lloyd's Register
Foundation

004684-004892-0235