



© 2020

Lloyd's Register
Foundation



WILTON-FLIENVOORT
SCHIEDAM - HOLLAND

COPYRIGHT WF INDRUK VERBODEN

Tomar

Crack after veeding out stb. side coupling
flange of stern frame.

Bij nabestelling opgeven Neg. Nr. N246 / 1

Datum Order Nr. 5131

3/15" Tomar.

10 ASSOCIATED

Lot.

Dated

9/63

© 2020

56874

Lloyd's Register
Foundation

SUBJECT:-