

COPY

LLOYD'S REGISTER OF SHIPPING

KRH/800



Port Karachi,

Date 7th May, 1965

This is to Certify *that I have surveyed part of the machinery of the s.s. "PAKISTAN PROMOTER" 6812 gross tons of Karachi for Completion of MBS, Conditions of Class and Repairs, as she lay afloat at Karachi, on 25th January, 1965 and subsequently*

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned MBS 8/64 as previously recommended, without the condition of class relating to the Centre Boiler Auxiliary feed check valve chest, but subject to:

~~Parts now examined:~~

- 1st Starboard feed pump water cylinder (Metalocked) being re-examined and dealt with as found necessary by the end of July, 1965.
- 2nd Forward main boiler not to be used until defective plain tubes have been renewed and its safety valves adjusted under steam.
- 3rd Sternbush lining (wear down 7.5 mm) being renewed and propeller rubber seal ring gland studs being specially examined and dealt with as found necessary both at the next drydocking on arrival of the ship at Karachi from her present voyage Karachi-Chittagong-Karachi and before the end of June, 1965.

P.T.O.

Surveyor to Lloyd's Register of Shipping
(J. van Son)


ABS Auxiliary Boiler Survey
CSM Continuous Survey of Machinery
DBS Donkey Boiler Survey
ES Engine Special Survey

MBS Main Boiler Survey
OF Fitted for oil fuel (date) FP above 150° F.
SGS Steam Generator Survey
SPS Steampipe Survey

TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



© 2020

Lloyd's Register
Foundation

204684.00 4892-0375

