

by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "ITOLA" Rpt. Hpl. No. 18061

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 14490 Depth "d" -
2nd Long. No. 38550 Proportions = $\frac{L}{D}$ 12.17 to Upper dk.
10 to Br. dk.

Framing As approved. Sheerstrake As approved.

This vessel is generally similar to the "ITINDA" and "INDORA".

The scantlings have been approved on the basis of a restricted draught of 25' extreme.

Ceiling has been omitted under the hatchways but the retaining angles have been fitted and it would appear that, as in the case of Messrs. Doxford's No.664 for the same Owners, it is intended to fit the ceiling when the vessel arrives in India. (See special indorsement 18.12.39).

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed ~~as~~ "100A" "With freeboard", subject to ceiling being fitted under the hatchways when the vessel arrives in India.

The Summer Freeboard as shown on the attached extract from the Freeboard Verification Form, now marked on the vessel's sides, to be inserted in the classification certificate and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying extract, to be inserted in the certificate of classification.

2 Dks.

Cell DB 366' 1127t, FPT 175t, APT 168t.

FK, 7BH, Cem., Lloyd's A & CP.

P.42' B 139' F 43'

O.L. 442.8'

a⁺
2"



[Handwritten signature]

© 2020

9.8.40.

The Surveyors should be informed it is concluded the spacing of the rivets in the side frames amidships is 5 1/4" as approved and that the length of the forecastle for record in the Register Book in accordance with Circular 1551 is 43' but they should state if this is so.