

COPY

Ship's name "SALAMMANNA"

Port Suz

No. 1892

Last survey date 29.7.63.

GB Class is subject to

For conditions of class see previous endorsement.

S.R.L. Appendix (as before or none)

Nature of present survey (afloat and in drydock)

Rear and tear and part subject item repairs.

Recommendation


SUBJECT to indented shell plate in way of No.4 hold (s.s) and structure in way and to indented sheerstrake and plating in 1st below in way of No.3 hold (s.s) also to indented shell plate in 'A' strake in way of No.6 D.B.tank (s.s) and keel plates aft being specially examined and dealt with as necessary next drydocking, and to shell plate in way of No.1 hold bilge (p.s.a) (cement box fitted) being specially examined and dealt with as necessary next drydocking, but without other conditions.

As Now. Subject
Without.

IN S.R.L. APPENDIX.

Indents in side shell plating (p.s.s).

Poop side (p.s) indented.



© 2021

Lloyd's Register
Foundation