

EA

COPY

Ship's name "SALAMMANNA"

Port

CCO.

No. 6693

Last survey date 1.2.63.

Class is subject to

indented shell plate in way of No.4 hold (s.s)
and structure in way being specially examined
and dealt with as necessary at the next drydocking.

S.R.L. Appendix (as before ~~or none~~)

Nature of present survey (afloat and in drydock)

Docking Deferred repairs to damage caused by contact.


Recommendation

SUBMITTED record of DS 2,63 be assigned,
subject as above and to indented sheerstrake and
plating in 1st below in way of No.3 hold (s.s),
also to indented shell plate in 'A' strake in
way of No.6 D.B. tank (s.s.) and keel plates aft
being specially examined and dealt with as necessary
next drydocking.

DS 2,63 Subject

IN S.R.L. APPENDIX

Indents in side shell plating (p & s).
Poop side (p.s) indented.



© 2021

Lloyd's Register
Foundation