

27 JUL 1964

Ship's name "SPABECK"

Port PLY.

No. 9061

Class is subject to

Last survey date 17.6.64.

None

S.R.L. Appendix (as before ~~xxxxxxx~~)

Surveys due SPECIAL SURVEY (C) due 8,63.  
Postponement until 8,64 approved 10.10.63.

Nature of present survey ~~xxxxxxx~~ in drydock)

Docking. Deferred repairs due to contact damage.

Is interim certificate in order

Yes/No/None  
~~xxxxxx~~

Items outstanding if any for SS

ALL ITEMS

SS proposed to be completed by


Recommendation SUBMITTED record of DS. 6,64 be assigned subject to buckled stem indented shell plates C.I., D.I. etc. (p & s) being specially examined and dealt with as necessary at next drydocking, but action be deferred for S.S. by 8,64

DS.64 Subject

Note:- It is stated on the report the vessel is now being laid up at Devonport and all repairs meantime deferred.

IN S.R.L. APPENDIX

Shell plates No.2 in forecassle sheer and 1st below (p.s) indented.



© 2021

Lloyd's Register  
Foundation



IT IS FURTHER SUBMITTED the Surveyors be  
advised in future similar cases any additional condition of  
class should also be reported on Rpt.8 in the space  
under recommendation.

23/7

44  
22-7-64



© 2021

Lloyd's Register  
Foundation