



LLOYD'S REGISTER OF SHIPPING

JAB/RT. 5th Floor, Commercial Union Building,
No. 1 Telegraph Street (P.O. Box 480),

BY AIRMAIL.

Singapore, 1


Reference

Telegrams: Surveyor

30th of March 1965

Telephone Nos. 95861 & 75112

The Secretary,
LONDON.



Dear Sir,

"WAVE SOVEREIGN"
(SNG.RPT.No.17987)

With reference to your Classing letter of 16th instant, we confirm the set up and indented shell plates A 16, B 17 (starboard side), C 9, 10 and 12 (starboard side) and D 10 and 12 (starboard side) were, in fact, specially examined and found to continue efficient, no repairs being considered necessary.

We regret omitting to state this fact in our Report.

Yours faithfully,

FOR THE SURVEYORS.

DR



© 2020

Lloyd's Register
Foundation

st

[Handwritten signature]

*Noted. SRS.
5/12/65.*

FOR THE SHIPBORN

YOUR OFFICE

our report.

We regret omitting to state this fact in
our report, no debate being considered necessary.
The fact, however, examined and found to continue
and IS. (approximately) and D 10 and IS (approximately) and
and II (approximately) and B II (approximately) and C O 10
and II (approximately) and C O 10 (approximately) and
with reference to your Chairman's letter of

(ENC. 10. 10. 1084)

UNSAFE COMMERCE

Dear Sir,

Yours faithfully,
The Secretary

Date of March 1962

RECEIVED

© 2020



Lloyd's Register
Foundation

BY AIRMAIL

No. 1 Telegraph Street (P.O. Box 480)

240 Floor Commercial Union Building

LLOYD'S REGISTER OF SHIPPING