

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

16th March 1965

C.

MK/BN

Dear Sirs,

CLASSING LETTER


17987 "WAVE SOVEREIGN". As recommended. Prior to your survey the class was subject to set up and indented shell plates "A" 16 B.17 (starboard side), C.9, 10 and 12 (starboard side) and D.10 and 12 (starboard side) being specially examined and dealt with as necessary at the next drydocking. It is concluded that these items were examined and found in satisfactory condition, but your confirmation is desired.

17992 "KAPETAN KOSTIS". As recommended. Prior to your survey the machinery class was subject inter alia, to the Metalock repair to Main Engine No.2 cylinder lower water jacket being examined by February 1965. As this repair was carried out in 1961 and has been found satisfactory at each annual examination since that time, it is thought this item could be transferred to the S.R.L. Appendix. However, before doing so, it is concluded the No.2 cylinder jacket was found good when this unit was examined, but your confirmation is desired.

Yours faithfully,

pro Clerk to the
Classification Committee.

The Surveyors,
SINGAPORE.



© 2020

Lloyd's Register
Foundation

004710-004717-0077