

7 APR 1953

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME "CAPE ST. DAVID" REPORT Rot No. 35861

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/52.

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

This case is stated in endorsement of 20.2.53. relating to electrical equipment.

In reply to queries contained therein, the Rotterdam Surveyors state that the generator cable size has been suitably increased.

They state, however, that the contractors could not supply the necessary circuit breakers, and the ammeter scales have not been altered.

They now ask for acceptance of these deficiencies from the Rules since the maximum required load on board will not exceed 20 KW.

Before replying to the Surveyors, SUBMITTED the Owners informed as above and be asked whether they have any objection to the acceptance of the electrical arrangements as now fitted.

Sub. 12/4/53.

Ent

2.4.53.

Row. J.S.



© 2020

Lloyd's Register Foundation

004718-004726-0180

... 2 recommended sets, delivered by the owners.