

WRECK  
SECTION  
No. 995

Part. 8.

DISCLOSED  
SECTION  
No. 995

WRECK  
SECTION  
No. 995

Received at London Office

Lon No. 129167 A

# REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of...  
No. in Reg. Book 27569  
Survey held at on the Wood, Iron or Steel M.V. SIREFTJELL  
Built at Gothenburg By whom Erikssbergs M.V. Aktiebolag  
When 1936 - 6  
Tonnage: GROSS 8477  
UNDER DE 7503  
NET 4899  
Owners AS Falkenberg & AS Dorell  
Managers Olsen, Ugelstad  
Owners' Address...  
Port belonging to Oslo

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage...  
Cell DBor DBa... feet: uE&B... feet: f... feet  
total capacity... tons, FPT... tons: APT... tons: MT... feet... tons.  
only alterations in the existing records of tanks should be inserted.  
N.B.—All alterations in the existing records should be underlined.

Last Report, No. 7486 Port...  
Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.  
Society's Freeboard (if assigned) as painted on Ship and now verified...  
Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place ..								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Caulking of Decks	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Coamings	Rudder	Scuppers	Boats
Beams & Fastenings	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
Outside Plating	Windlass	Hatches	Condition, how ascertained
" " in way of sidelights	Have pumps been examined and found efficient?	Planking	(State if wedges removed.)
Frames	Have Sluice Valves been examined and found efficient?	Caulking	Equipment letter
Reverse Frames	Have Watertight Doors been examined and found efficient?	Treenails	Anchors, No. of
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Cables (State if now ranged)
Transverses	Air and Sounding Pipes	Transoms, Pointers & Crutches	" length mean diamr.
Floors	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	(on board.)
Keelsons		" " at other places	" Rule length size
Stringers		Stringers, Clamps & Shelves	Chain Locker
Inner Bottom Plating		Salting	Hawsers & Warps
Have the Tanks been examined internally?		State if examined	Standing and Running Rigging
Have the Tanks been tested?			Sails

General Observations, Opinion as to Class, Recommendation, &c.:  
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 23)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Section 23)	£	:	:	19.
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19.

Committee's Minute... FRIDAY - 5 AUG 1955  
Character Assigned...  
Surveyor to Lloyd's Register of Shipping.  
GENERAL COMMITTEE Thursday, 22nd September, 1955  
Classing Committee's decision confirmed

Wreck Section No. 995  
at Owners' request  
Conversion

004727-004735-004740

WRECK  
SECTION  
No. 995

In Certificate required? if so, to be...