

fees paid

insured by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Steel Sc. M.S. "BRITISH DILIGENCE" Rpt. Nwc. No. 95139

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 15801Depth "d" -2nd Long. No. 44466Proportions = $\frac{L}{D}$ 13.63

Framing Longitudinal framing at bottom Sheerstrake 1.08
Transverse framing at sides (.98 approved)

This is a sister ship to the "ABBEYDALE"

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A1 "Carrying Petroleum in Bulk"

1 Dk. 2nd Dk. clear of cargo tanks, "Longitudinal framing at bottom and at deck".
 Cell. DBuE 75' 176t, DTf 34' 397t, FPT 209t, APT 183t.

FK, 17 BH, pt. Cem., pt. Asp., Lloyd's A & CP.

P 107', B 43', F 45'.

Machy Aft.

O.L. 481'-7"

[Signature]
[Signature]
 15.6.37



© 2021

Lloyd's Register
Foundation

004755-004760-028