


"MINA MARY"

Rpt. Bbo. No. 10282

It is submitted before this case receives consideration the Surveyors be requested by cable to state whether the equipment of anchors, chain cables and ropes now on board the vessel is sufficient for her service.

They should be informed by letter it is concluded the thickness of the double bottom centre girder within the $\frac{1}{2}$ -length amidships is 8 mm as approved, but they should state if this is so.



© 2021
J.M.D. / J.C.D.
23.8.48
Lloyd's Register
Foundation

004769-004777-0052

ships

... of remainder in Holds