

2 AUG 1959

Received from Chief Ship Surveyor

SHIP'S NAME "HOLDERNOOK" REPORT Cff. No. 60913

VC

Outstanding Conditions of Class: SUBJECT to set up keel and 'A' strake (s.s.) plating, forward and aft, being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix. (~~As before~~ or None)

Nature of Present Survey: (Afloat and ~~in dry dock~~)

Temporary repairs on account of contact damage.

Recommendation: SUBJECT as above, and to stem and stem plating being specially examined and dealt with as found necessary by the next drydocking not later than 10.59.

As now. SUBJECT.



© 2021

Lloyd's Register
Foundation

Blk (new)

AS Annual Survey
BIS Biennial Survey
DS Docking Survey

SS Hull Special Survey
SS(Dr) Hull Special Survey (Drilling)
SS(M) Hull Special Survey (Modified)

004769-004777-0163

s classed