

Report of Survey for Repairs, &c., of Engines and Boilers.

of writing Report Jan 8th 1924 When handed in at Local Office Jan 22nd 1924 Port of GLASGOW.
Survey held at Glasgow Date, First Survey and Last Survey Jan 5th 1924.
on the Machinery of the Wood, Iron or Steel SS. HOMEWOOD.
Gross 870 Vessel built at Workington By whom R. Williamson & Sons Ltd When 1926.
Net 426 Engines made at Coatbridge By whom W. Beardmore & Co Ltd When
Main Boilers 1 Boilers, when made (Main) (Donkey)
Owners Joseph Constantine & S. S. Line Ltd Owners' Address
Managers Port Voyage
If Surveyed Afloat or in Dry Dock Govan No 2 Dock. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Report No. Port
Particulars of Examination and Repairs (if any) Damage.
Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on damage (the cause of which must be stated) should be separated from repairs due to other causes; and being detailed in the body of the report, should be briefly summarised at the end of the report. State also the initials of any letters respecting this case.
In cases where the Surveyor has not made a special damage report he is required to state whether he has examined the services for this purpose, and why they were declined Damage Report made.
Damage report made by anyone else? If so, by whom? Thomas Niccol
Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey
not done, state for what reasons?
Parts of the Boilers could not be thus thoroughly examined?
Special means, in the absence of internal examination, were adopted by the
to assure himself of the thorough efficiency of those parts of each Boiler?
Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?
Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?
Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boiler?
Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boiler?
Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boiler?
Shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? No
Now been changed? No If so, state reasons
Now fitted new? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?
Distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft? 1/32"
Is not complete, state what arrangements have been made for its completion and what remains to be done? Complete.
Damage stated to have been sustained while shifting vessel in harbour at Workington on 10th November 1926.
A portion of one blade of cast-iron propeller broken off.
Shaft drawn, examined and found in good condition
Propeller fitted
Outside fastenings of stern tube and sea cocks

Observations, Opinion, and Recommendation:—
Early what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, E.S. 9, 11, E.&M.S. 9, 11, or L.M.C. 9, 11, 10, 11, F.D., &c.)
Forwarded for the information of the Committee

er Section 28) £ : : Fees applied for 22 JAN 1927
to or Repair Fee (if any) £ 2 : 2 : 0 Received by me, 9-3-1927
g Expenses (if chargeable) £ : :
nittee's Minute GLASGOW 25 JAN 1927
ned See accompanying machinery report
004769-004777-0182
FRI. 17 AUG 1928
FRI. 11 FEB 1927
WED. 3 AUG 1927
D. C. Barr. © 2021
Engineer Surveyor to Lloyd's Register of Shipping.
TUES. 1 FEB 1927 TUES. 6 SEP 1927
FRI. 4 FEB 1927 TUES. 15 MAR 1927
TUES. 17 MAY 1927
TUES. 26 JUL 1927

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

ॐ नमो भगवते वासुदेवाय

Lepidoptera

attained only by continuous and not

The reason for this is that the
 1891 volume is not yet published
 and the volume for 1892 is not yet
 published. The volume for 1893
 is not yet published. The volume
 for 1894 is not yet published.

14.001. *aparin* *Conrad*.
Staphylinidae *no*

above supply of animals
possibly abundant

John R. C. M. moved

Co. 22 HOWE MOOD.

100 of 10000

© 2021

Lloyd's Register
Foundation