

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
 Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

21st June 1965

C.

MK/BN

Dear Sirs,

M.S. "DURHAM"

When this ship was surveyed at London during April the chain cable was run out into a Barge in order to verify the amount of cable on board.

The chain cable was found to be 60 fathoms below Rule requirements and, in the circumstances, class has now been continued subject, inter alia, to 60 fathoms of chain cable being supplied at the earliest opportunity and I shall be glad to learn what arrangements you propose to make to deal with this matter.

The Auxiliary Boiler Survey was completed at London and a record of ABS 9.64 has now been assigned.

Yours faithfully,

pro Clerk to the
Classification Committee.

The Federal Steam Navigation Co.Ltd.,
Beaufort House
Gravel Lane
LONDON E.1



© 2020

Lloyd's Register
Foundation

004789-004798-0244