

PT

3 FEB 1965

Ship's name "DURHAM"

Port WLN

No. 10,597

Class is subject to

Last survey date 18.1.65

No.10 keel plate from fwd. (temporarily repaired 12.61) and to indented shell plate H.17 (p.s. from fwd) being specially examined and dealt with as necessary by the S.S.

S.R.L. Appendix (as before ~~or xxxxxxxx~~)

Surveys due SPECIAL SURVEY (C) due 10.64. Postponement until 7.10.65 approved 4.11.64. G.E. held 9.64.

Nature of present survey (afloat and ~~in drydock~~)

Equipment:- Damaged 2 short lengths of chain cable removed.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS

SS proposed to be completed by

Recommendation SUBMITTED ACTION be DEFERRED for Special Survey by 10.65, subject as above and to 15 fathoms of chain cable being supplied at the earliest opportunity.


SUBJECT

IN S.R.L. APPENDIX

Shell plates G.7, H.4, M.17 & 18 (p.s. from fwd) indented.

Shell plate L.8 (p.s) indented.

No.3 hold after bulkhead (s.s) slightly buckled.



Lloyd's Register
Foundation