

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
 { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

30th October, 1964

C
DHGK/RW

Dear Sirs,

CLASSING LETTER

14650 "DURHAM". As recommended, except that the hull condition of class should be dealt with at the Special Survey.

It is concluded that the structure under the boilers has been generally examined at this time, but confirmation is desired.

It is noted on the Rpt. 9A that the windlass has been examined but omitted from the Interim Certificate. Your comments are desired, and, if necessary, an amended Interim Certificate should be issued.

Yours faithfully,

pro Clerk to the
Classification Committee

The Surveyors,
FALMOUTH



© 2020

Lloyd's Register
Foundation

004789-004798-0260