

29 OCT 1964

EA
Ship's name "DURHAM"

Port FAL No. 14650

Last survey date 29.9.64

Class is subject to

No.10 keel plate from fwd. (temporarily repaired 12,61) and to indented shell plate H.17 (p.s.from fwd) being specially examined and dealt with as necessary by the S.S.

S.R.L. Appendix (as before ~~of XXXXXX~~)

Surveys due

SPECIAL SURVEY (C) due 10,64. Postponement until a later date approved 24.7.64 provided a satisfactory G.E. is held in drydock, period of postponement being dependent upon the reported results of G.E.

Nature of present survey (afloat and in drydock)

Docking: General Examination as above.
Damage repairs - H.W.
Wear and tear repairs.

Is interim certificate in order Yes/No/None

Items outstanding if any for SS

ALL ITEMS

SS proposed to be completed by

Recommendation SUBMITTED record of DS 9,64 be assigned, subject as above.

DS 9,64 Subject.

IN S.R.L. APPENDIX

Shell plates G.7, H.4, M.17 & 18 (p.s.from fwd) indented.

Shell plate L.9 (p.s) indented.

No.3 hold after bulkhead (s.s) slightly buckled.

IT IS FURTHER SUBMITTED postponement of the S.S. until 10,65, merits approval.

IT IS ALSO SUBMITTED the Surveyors be advised it is concluded the structure under the boilers has been generally examined at this time but confirmation is desired.

Lloyd's Register Foundation
See letter 3/11/64
19/10/64