

# LLOYD'S REGISTER OF SHIPPING

FOUNDED 1780

RE-CONSTITUTED 1834

## Certificate of Class

Motorship "SEISTAN"  
Official Number 187620 Port of Registry London  
Owners Strick Line Ltd., (F.C.Strick & Co. Ltd., Managers).  
Builders, and where and when built John Readhead & Sons Ltd., South Shields, July 1957.

REGISTERED TONNAGES  
Gross 7440.13  
Net 4333.68

MOULDED DIMENSIONS  
Length 450 ft. 0 ins.  
Breadth 58 ft. 3½ ins.  
Depth 32 ft. 3 ins.

This is to Certify that this Ship has been built under the Special Survey of the Surveyors to this Society, and was reported to be, on the 31st July 1957 in a fit and efficient condition as is prescribed by the Society's Rules for the safe carriage of dry and perishable or other approved Cargoes, and has been CLASSED and entered in the REGISTER BOOK of this Society, with the Character  100A1

subject to Periodical Surveys as required by the Rules.


The approved minimum freeboards from the deck line are as follows:—

Tropical 6 feet 2¼ inches (T).  
Summer 6 feet 8¾ inches (S).  
Winter 7 feet 3¼ inches (W).

Winter North Atlantic } — feet — inches (WNA).  
Allowance for fresh water for all freeboards } 6¾ inches

Witness my hand,

  
Secretary


  
Chairman.

71, Fenchurch Street, London, E.C.3. 27th September 1957.

N.B.—If the ship herein named proceed to sea with a less freeboard than that approved by the Committee, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

“ While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors or other Officers or Agents of the Society.”



Lloyd's Register  
Foundation



© 2020

Lloyd's Register  
Foundation

004833 - 004841 - 0027