

5m.12.46.

an

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

110 MAR 1948

VESSELS NAME "CANTICK HEAD"

REPORT

Nwc.

No. 105076

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

The class is subject to permanent repairs to indented shell plating, wood belting, etc. on starboard quarter being effected at the first convenient opportunity.

The NEWCASTLE Surveyors report the vessel placed on slipway, bottom coated, and on account of collision and contact with quay wall DAMAGE, repairs effected to shell plates, frames, bulwarks, wood belting, and minor items.

Indented shell plating, etc., as above, now dealt with.

IT IS SUBMITTED the vessel is eligible to remain as classed, with record of docking survey 2.48, but without special condition.

2.48. Wal., without.



© 2020

q.3.48.

Lloyd's Register
Foundation

004849-00488-0087