

Received from Chief Ship Surveyor.....

25 SEP 1959

SHIP'S NAME "HERBRAND"

REPORT

Msl.

No. 12643

VC

Outstanding Conditions of Class: SUBJECT to a bower anchor and 45 fms. of chain cable being supplied at the earliest opportunity, and to indented shell plates F.3 and G.3 (ssf) being specially examined and dealt with as necessary next drydocking ACTION is DEFERRED for Special Survey by 11.59

R.L. Appendix. (As before ~~or None~~)

Surveys due: SPECIAL SURVEY (C) due 6.59 Postponement until 11.59 approved 22.4.59

Location of Present Survey: (Afloat and ~~in dry dock~~)

Equipment - supply and verification of a bower anchor and 45 fms. of chain cable as above.

Special Features:

Interim Certificate in order (Yes-~~No-None~~)

Items Outstanding: (If any for S.S.)

All items

to be completed by: 11.59

Recommendation: SUBJECT to indented shell plates F.3 and G.3 (s.s.f) being specially examined and dealt with as necessary next drydocking, WITHOUT other condition, but further ACTION continue to be DEFERRED for Special Survey by 11.59.

SUBJECT WITHOUT



© 2020
25-9-59

Lloyd's Register
Foundation

004866-004872-0171