

"HERBRAND"

In December 1949 the Owners stated that they intended to alter the oil fuel overflows from the service tanks, in accordance with the arrangements now in force, when new main engines were fitted at Bremen in the early part of the following year.

No mention thereof was, however, made in Bremen report No.149 in connection with the Special Survey and installation of the above engines. The Surveyor was not at the time requested to confirm that the necessary alterations to oil fuel overflows had, in fact, been made, but it is concluded such alterations were effected. This will, however, require to be confirmed, and IT IS THEREFORE SUBMITTED the following note should be made in the Special Reasons List:-

"Alterations to overflow pipes from oil fuel service tanks in accordance with Circular 1927 to be verified."

Note for SRL
Eps. Med DK 8/6/51



1. 6. 51.
© 2020

Lloyd's Register
Foundation

004866-004872-0192