

-8 JUN 1966

REPORT 8

SHIP'S NAME

ANGELIC

PORT

COCHIN

No.

330

NIL/

LAST SURVEY DATE

26-4-66.

CLASS IS SUBJECT TO NIL

~~XXXXXXXXXX~~


SURVEYOR REPORTS DAMAGE TO PROPELLER BLADES
DUE TO CONTACT, NO REPAIRS WERE EFFECTED
& IT IS RECOMMENDED PROPELLER BLADES
BEING SPECIALLY EXAMINED & DEALT WITH AS
NECESSARY AT NEXT DRY DOCKING

C.S. Adolwood.

It is submitted that this
case is eligible to remain
as CLASSED. SUBJECT AS
NOW RECOMMENDED

SURVEYOR SHOULD BE ADVISED A REPORT
9 SHOULD BE SUBMITTED FOR MACHINERY
SURVEYS & BE GUIDE RECOMMENDED IN
FUTURE.

X 9/6



© 2020

Lloyd's Register
Foundation

004873-004880-0267