

Ship's name "SEVERN RIVER" Port LGN No. 1932
Last survey date 16.5.64
Class is subject to

a bower anchor being supplied
at the earliest opportunity.

S.R.L. Appendix (as before ~~or name~~)

Nature of present survey (afloat and ~~in drydock~~)

Supply and verification of a
bower anchor as above.

Recommendation

SUBMITTED the ship is eligible to remain
as classed, without special conditions.

As Now Without.

IN S.R.L. APPENDIX

Indents in shell plating (p & s).

Bottom plating slightly wavy.

OFFICE NOTE

Bottom plating and inner bottom plating in
No.3 hold stiffened - Rot.11,52.
Crack arresters fitted to upper deck
beam 54-155 (p & s) - St.J 3,53.

© 2020

Lloyd's Register
Foundation