

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

3rd December, 1963

C.

MK/BN

Dear Sir,

CLASSING LETTER

2051 "HERMON". As recommended, except that a record of MBS 6.65 has now been assigned.

It is concluded you are in error in reporting 3 bower anchors on board as the class is subject to a bower anchor and 30 fathoms of chain cable being supplied at the earliest opportunity and no record appears in this Office of a bower anchor having been supplied, and in the circumstances I shall be glad to receive your comments regarding this matter.

With regard to the machinery I shall be glad if you will state the wear-down of the sternbush before re-wooding.

2049 "LELETA". As recommended except that a record of ABS 9.65 has now been assigned.

Yours faithfully,

pro Clerk to the
Classification Committee.

C. G. Gaddolfo Esq.,
LEGHORN

© 2020

Lloyd's Register
Foundation

004881-004886-0108