



Lloyd's Register of Shipping.

HEAD OFFICE: 71, FENCHURCH STREET, LONDON, E.C. 3.

Port of Piraeus,

Odos Notara, 50^a, 19th February, 1960.

RECEIVED

22 FEB 1960

And

Communications to be addressed to
THE SURVEYORS.

(S)

Dear Sir,

"GEORGIOS MANOLAKIS"

We are in receipt of your correspondence of the 21st ultimo referring to the Electrical Installation of the above captioned vessel and have to advise you that this vessel is no longer at this port but trading on the American Coast. We are therefore unable to reply to your queries A. & B. at this time.

With respect to the Pump Room lighting the lights are fitted in the Pump Room Casing and the Owners have been advised that the glazed ports be cemented in place, as have the requirements for the midship tween deck space lighting.

We would confirm that the towline and mooring ropes were in accordance with the Rules.

We regret the delay in replying to your correspondence but it is due to the pressure of work experienced at present.

Yours faithfully,

B. J. Keir

The Secretary,
London.



© 2020

Lloyd's Register
Foundation

CLASSIFICATION

H AM

The Pir. Surveyor should be reminded that F.E. Rpts on the boats are required as per the letter of 21/1/60. Regarding items (a) & (b) of the which port a surveyor should visit the ship to get the required information & the Owner should give early advice so that the surveyor may be advised in good time.

Q 22/2/60

The Secretary,

London.

It is due to the pressure of work experienced in the past that we regret the delay in replying to your letter of 21/1/60 in accordance with the Rules.

We would confirm that the towing and mooring charges for the night between dock and berth are fixed by the Board of the Port of London Authority and are not subject to negotiation. We have the pleasure to advise you that the charges have been advised to you in the form of a circular letter of 21/1/60.

With respect to the Board Room lighting the rights are reserved to you under V. & B. at this time.

This Board has decided on the American Contract. We are therefore unable to advise you that this contract is no longer in force. We are referring to the Electrical Installation of the above captioned vessel.

We are in receipt of your correspondence of the 21st ultimo.



© 2020

Lloyd's Register Foundation



REGISTRATION DOCUMENT

5 FEB 1960

RECEIVED

Box of Papers

HEAD OFFICE: 31 BENCHURCH STREET, LONDON, E.C.3.

REGISTRY OF SHIPPING

REGISTRY OF SHIPPING