

Lloyd's Register of Shipping.

HEAD OFFICE: 71, FENCHURCH STREET, LONDON, E.C. 3.

Port of Piraeus,

Odos Notara, 50^a, 16th November, 1959.

W addressed to
ORS.

RECEIVED

20 NOV 1959

ANS'D

Dear Sir,

"GEORGIOS MANOLAKIS"

With reference to your previous correspondence of the 24th September last relative to the above named vessel we beg to advise you that all cables are rubber lead armoured and that fuses are of Siemens manufacture, in all distribution boxes these are of the reset automatic cut out type.

With regards the pump room lighting, the lamps are enclosed in welded steel frames having heavy glass ports. The joint between glass and box is maintained by a heavy rubber ring.

The Owners have been informed of your request for a plan showing lighting of main, midship tween deck space, and pump room spaces and have put the matter in hand but as yet nothing has been received at this office.

Yours faithfully,

E. R. Reul

The Secretary,
London.



© 2020

Lloyd's Register
Foundation

004881-004886-0130

MOISTURE
TESTS

**Lloyd's Register
Foundation**

Odoo Motes, Po f, Tech Members, IQRo.

Lot of Blister,
HEAD OFFICE : 17, Lanchinch Street, London, E.C. 3.
TELEGRAMS : SHIPPIKING.

© 2020



SHIPPING
SOCIETY

WILLIAM H. COPE, SECRETARY.

CHORCHILL'S MANUFACTURERS.

181

WITH reference to your previous correspondence, we beg to advise you that the proposed new system of classification of ships, in its present state, will not be adopted by the Society, but will be modified to meet the requirements of the shipping community.

We have, however, given consideration to the proposal, and it has been decided to submit it to the members for their consideration.

It is intended to submit the proposal to the members at the Annual General Meeting, to be held on the 21st October, and to give the members an opportunity to consider it, and to propose any alterations or modifications which they may desire.

Yours truly,

The Secretary,
London.

ASSIFICATION