

Chief Surveyors.....

Received from Chief Surveyors.....

SHIP NAME Steel Screw "FORT AMHERST" Report Gls. No. 56500

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey First Entry When due --

*100A1

With Freeboard

2 Dks. 3rd Dk. in forward holds.

Cell. DB 247' 435t, FPT 23t, APT 64t.

FK, 7 BH (2 BH to 2nd Dk.), pt Cem. Lloyd's A & CP,.

P & B 200', F 47'



© 2020

Lloyd's Register
Foundation

004881-004886-0164