

Rpt. 8

REPORT OF SHIP SURVEYS AND REPAIRS
FOR CONSIDERATION BY THE COMMITTEE OF LLOYD'S REGISTER OF SHIPPING

Ship's Name ~~XSS~~/MS "Stirlingshire" Port Daressalaam

Processing Number: LR 35856 Gross tons 6987 Rpt. No.

Port of Registry Glasgow Date of build 1945 Is there a Rpt. 9?

No. of visits 2 First date 29.6.66 Last date 1.7.66

Cert. B Issued & copy herewith? Yes Damage rpt. issued & copy herewith? Yes Last rpt. (H.Q. only) MBA 300

Date of completing rpt. 1.7.66 Surveyed at, if different from Port above Report No. 8/66

Safcon Cert. (ST) issued & copy herewith? If surveyed in D.D. last date of examination Invoice No. LL 504393

Has a Load Line Survey been held? No Summer freeboard as verified

28 JUL 1966

State which additional Rpt. 8 is attached: (Cont); (A); (DR); (EQ); (Rig)

Survey fees £14.0.0 Damage fee Expenses £2. 0. 0

Agents £ 2.16.0

L.R. £ 2.16.0

£19.12.0

S.A. fee

I have surveyed the above-named ship in accordance with the Rules for damage caused by scaling to shell plate at stern stated to be plate H1 Starboard side. This was found to have a ragged hole about the centre of the strake and just aft of frame No.1 and whole of plate exceeding thin. To be patch repaired and re-examined at Mombasa to which port the ship is bound.

Repair hose tested and found watertight.

I declare that the items detailed in this report (except as stated otherwise) comply with the requirements of the Merchant Shipping (Cargo Ship Construction and Survey) Rules 1965, applicable to this ship, and are in all respects satisfactory for the service on which the ship is intended to ply namely International voyages/voyages within the limits

Dar es Salaam - Mombasa

(The above declaration applies only to sea-going cargo ships of 500 tons gross and above registered in the U.K.)

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. I recommend, therefore, that this ship remain as classed with ~~XXX~~ fresh record of dry docking.

until satisfactory repair is carried out at Mombasa.

MBA 19/7

ALSO FOR
SPL FOR
TRO
SRL
POSTING
HEADER
CERT

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the Interim certificate.)

Date of Committee TUESDAY - 6 SEP 1966

Minute

Deferred for SS subject (how)

RP Johnston
Ag Surveyor to Lloyd's Register of Shipping

Water Amt check (Page) 004 887-004892-0127

Lloyd's Register Foundation
FOR CHAIRMAN
CLASSN. CITEE

taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and action

†The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due