


LLOYD'S REGISTER OF SHIPPING



Report No. 8 / 66
Invoice No. L.L. 504393

Port..... DAR ES SALAAM

Date..... 1st July, 1966

This is to Certify that I have

*surveyed the M/V "STIRLINGSHIRE" LR35856 Gross tons 6987
for the purpose of examining structural damage to the shell plating
at the after end Starboard Side stated to be plate H1.*

*and that I am transmitting to the Committee of Lloyd's Register of
Shipping, London, a report, stating that all repairs recommended by
me have been completed to my satisfaction, also that I am
recommending that she be allowed to proceed to Mombasa for re-examination
and more permanent repairs to this plate. Voyage restricted to
coastal voyage Dar es Salaam - Tanga - Mombasa.*

.....
Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BIS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	CSH	Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B 20m,3,63 (MADE AND PRINTED IN ENGLAND.)

004887-004892-0129