

SM. Ship's name "STIRLINGSHIRE" Port Mba. No. 3011

Last survey date 11.7.66

Class is subject to

For condition of class see previous endorsement.

S.R.L. Appendix (as before ~~or none~~)

Surveys due SPECIAL SURVEY (C) due 2,66. - postponement until 7,66 approved 7.3.66. Further postponement until 8,66 approved 9.5.66. ✓

Nature of present survey (afloat and in drydock)

Temporary repairs to shell plating.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS

SS proposed to be completed by

Recommendation

SUBJECT to local corrosion on sternframe (s) and indented shell plate No.10 in 4th below sheer (p), indented shell plate etc., No.7 from aft 3rd below sheer (s) and set in shell plates G.8 & H.7(s from a) being specially examined and dealt with as necessary next drydocking, also to 15 fathoms of chain cable being supplied at the earliest opportunity, and to shell plate H.1 (s from a) being specially examined and dealt with as necessary by 10,66 but ACTION be DEFERRED for S.S. by 8,66. ✓

S.R.L. APPENDIX (Amended)

Sheerstrake plating abreast fore and main masts (p) set in ✓

(External cathodic protection fitted 2,64).

Shell plating (p) indented.

© 2020

TO NOTE		
S. PLANS	S. RESEARCH	S. DEVELOP.
FREEBOARD	E. REPORTS	PUBS.

DM 27/7/66