


COPY

LLOYD'S REGISTER OF SHIPPING

Rpt. No. 3012



Port..... Mombasa,.....

Date..... 12th July, 1966......

This is to Certify that I have

surveyed the m.s. "STIRLINGSHIRE" *gross tons* 6987 of Glasgow,
for damage to the Hull at starboard side of stern caused by
wastage, as the vessel lay alongside the quay at Mombasa on
6th July, 1966

*and that I am transmitting to the Committee of Lloyd's Register of
Shipping, London, a report, stating that all repairs recommended by
me have been completed to my satisfaction, also that I am
recommending that she be retained as now classed without fresh
record of survey, but subject to holed plate H1 S.S. from aft
being specially examined and dealt with as necessary within
three months and subject also to any other conditions remaining
as previously recommended.*

R. Dunford

R. Dunford/

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BiS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	CSH	Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, but it is to be understood that neither the Society nor any Member of any of its Committees nor any of its Officers, Servants or Surveyors is under any circumstances whatever to be held responsible or liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any act or omission, default or negligence of any of its Committees or any Member thereof, or of the Surveyors, or other Officers, Servants or Agents of the Society."

N. Cert. B 240m,9,65 (MADE AND PRINTED IN ENGLAND.)

004887-004892-0132