

112 JUL 1966
9961 701 21

SHIP'S NAME

"STIRLINGSHERE"

PORT DSM

No. 5/66

A: NIL

LAST SURVEY DATE 15.6.66

CLASS IS SUBJECT TO :- Centre aux. diesel eng. being run on test on completion of assembly.

ABS dmt 7.66 not held
TS(C4) dmt 1.66 not held (see letter 9/5/66)
The Surveyor reports the steam engine crankshaft of auxiliary SW circulating pump cracked circumferentially 1 1/2" in way of crankpin bearing the pin appears to have been metal sprayed and the crack only extends the depth of the sprayed metal.

This now recommended the auxiliary SW circ pump steam engine crankshaft being specially examined & dealt with as found necessary on arrival at Lombasa where bound.


It is submitted that this vessel is eligible to remain as CLASSED. subject as recommended as above.

2/5 MBR

24.6

DAM M

6.66 DAM HTM



© 2020
27.66

Lloyd's Register
Foundation

004881-004892-0136