

sl

~~XXXXXX~~  
0044

12 AUG 1965

Ship's name "STIRLINGSHIRE"

Port LON

No. 154389

Class is subject to

Last survey date 23.6.65

24/5/65 ADP  
For conditions of class see previous endorsement.

S.R.L. Appendix (as before ~~xxxxxxx~~)


Nature of present survey (afloat ~~xxxxxxxxxxxxxx~~)

Further temporary repairs to midship deep tank.

Recommendation

SUBJECT to local corrosion on sternframe (s.s) and indented shell plate No.10 in 4th below sheer (p.s), indented shell plate etc. No.7 from aft 3rd below sheer (s.s) and set in shell plates G.8 and H.7 (s.s. from aft) being specially examined and dealt with as necessary next drydocking, also to 15 fathoms of chain cable being supplied at the earliest opportunity, and to structure in midship deep tank being specially examined and dealt with as necessary next Special Survey, - tank not to be used as such mean time.

As Now. Subject  
Amended.



Lloyd's Register  
Foundation  
P.T.O. ✓

IN S.R.L. APPENDIX

Sheerstrake plating abreast fore and main masts (p.s) set in.  
Shell plating (p & s) indented.  
(external cathodic protection fitted 2.64).

*DA. 27/7/65.*



© 2020

Lloyd's Register  
Foundation