

24. Jun 1961

Ship's Name ~~XX~~/MS "STIRLINGSHIRE"
LR. 534109

Gross tons 6987

Is there a rpt. 9? No

Port Middlesbrough Rpt. No. 23544

No. of visits 2

First date and

Last date 18.6.65.

Interim Cert. issued
& copy herewith?

Damage rpt. issued
& copy herewith? No

Last rpt. (H.Q. only) HVL 70489

Date of _____

21.6.65.

Surveyed at, if different from Port above —

Surveyed afloat

Afloat

Last date of examination in D.D. —

Has a Load Line Survey been held?

No

Freeboard Marks verified No

State which additional Rpt. 8 is attached: ~~CONFIDENTIAL~~

Survey fees

Damage fee

Expenses

£8:0:0d.

—

4s:Od.

S.A. fee —

We

X have surveyed the above ship in accordance with the Rules for Pressure testing of amidship deep tank.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

At request of Owner's representative attended on board for pressure test of amidship deep tank, following repairs which has been made without survey. Deep tank top port side and starboard side of forward bulkhead plating found to be wasted and leaking, as time and ship's commitments did not permit full survey or further pressure test of tank being made, cement boxes were fitted to the two wasted areas as above and it is recommended that the class be continued subject to the deep tank being specially examined, pressure tested and dealt with as found necessary on ship's arrival at London to which port she is now proceeding direct.

(Explanatory letter and copy of Interim Certificate forwarded to London Outdoor Surveyors for information 19.6.65.)

We

X recommend that this ship remain as classed ~~xxx~~/without fresh record of dry docking subject to deep tank being specially examined, pressure tested and dealt with as found necessary on ships arrival at London to which port she is now proceeding direct, also subject to any other conditions at present attached to the ship's class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Surveyor to Lloyd's Register of Shipping

Date of Committee

MONDAY 1 6 AUG 1965

Minute

See MON 154389

Lloyd's Register
Foundation

004887-004892-0187

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described, as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due